

# InRouter6XX-S-V2.3.0.r5550 Release Log

## Updates:

1. Fixed known security vulnerabilities. (These vulnerabilities were discovered by Zhouyuan Yang of Fortinet's FortiGuard Labs.)
2. Will execute AT+CFUN=1,1 to restart the module when the cellular network cannot be registered for a long time in FB53.
3. Fixed the problem that cannot establish new TLS connection when SSL\_ERROR\_SYSCALL occurs in the ATM sslProxy service.
4. Fixed nvram deadlock problem.
5. Fixed abnormal display in webUI when configuration in webUI does not change.
6. Update Copyright to 2023.